# **CREE ÷** LIGHTING<sup>®</sup>

INSTALLATION INSTRUCTIONS

### **IMPORTANT SAFEGUARDS**


When using electrical equipment, basic safety precautions should always be followed including the following:

## **READ AND FOLLOW ALL SAFETY INSTRUCTIONS**

1. To reduce the risk of electrical shock, turn off power supply before installation or servicing.

## SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE

**TO INSTALL:** 



© 2021 Cree Lighting, A company of IDEAL INDUSTRIES. All rights reserved. For informational purposes only. Content is subject to change. See www.creelighting.com/warranty for warranty and specifications. Cree® and the Cree Lighting logo are registered trademarks of Cree, Inc. XSPTM is a trademark of Cree Lighting, A company of IDEAL INDUSTRIES.

#### STEP 1:

Locate the (2) center bosses on top of the luminaire and insert front tabs of the bird spike kit behind the bosses. See **Figure 1. NOTE:** For XSP2 luminaires locate the (2) center bosses closest to the front edge of the luminaire. See **Figure 1.** 

#### STEP 2:

Press down on the middle bracket until it snaps into place. See **Figure 2.**