Page 1 of 3 CREE TEST REPORT FOR INGRESS PROTECTION (IP)

Test #: 6515Q Product Model Number: XCC LOW COST CANOPY

SAMPLE #2 FROM TEST "P". IP66 TEST WITH LIGHT GREASE ON FOAM-N-Product Description:

PLACE. NO SENSOR. RAN AT 700mA, 350mA AT THE LED'S.

MOUNTED TO EXPANDED METAL OVER J-BOX. SEALED AROUND J-BOX AND **Product Configurations:**

MOUNTING SCREWS WITH SILICONE.

Driver Manufacturer: **Philips** Driver Catalog #: 929000702202

IEC 60598-1 Edition 7.0 Applicable Specifications:

Test Results: (Based on Applicable Compliance Specification acceptance criteria.)

Dust Test IP6X:	X Pass	Fail NA	Test Performed By:	BRETT ROMANOWSKI
Screw or Cord Gland Location		Screw Diameter or Cord Gland ID	Number of Screws	Torque Applied

Start Time: 15:20 Operational Test Duration: 16 HOURS 30 MINUTES Start Date: 6/11/2013

Chamber Start Date: 6/12/13 Start Time: 7:50 Chamber Test Duration: 3 HOURS 5 MINUTES

Hypot Test Voltage: 1.96 kV Hypot Test Value: 4.39 mA Hypot test Duration: 60 sec

Comments: NO SIGN OF TALCUM DEPOSITS. Input Voltage: 120.1 Volts

Humidity: 41.8 % Air Temp: 23.5 °C Pressure: 986.7 mbar

Equipment ID #: 3213 3262 3098 3133 3246 8028 Cal. Due Dates: N/A 3/25/14 12/19/13 12/20/13 2/1/14 2/19/14

¬ ган

Equipment ID #: Cal. Due Dates:

Not Toot IDVC.

Wet Test IPX6:	X Pass	Faii	NA Test Perfo	rmea By: K	EVIN ARNDI
Screw or Cord Gland Location		Screw Diame Cord Gland	HNUmber o	f Screws	Torque Applied

Start Time: 4:40 Operational Test Duration: 15 HOURS 40 MINUTES Start Date: 6/10/2013

Product Tested Date: 6/11/13 Start Time: 8:20 Test Duration: 3 MINUTES

Hypot Test Voltage: 1.96 kV Hypot Test Value: 4.07 mA Hypot test Duration: 60 sec

Input Voltage: 120.1 Volts Comments: NO WATER ENTRY

Water Temp: 16.8 °C 47.7 % Humidity: Air Temp: 22.8 °C Pressure: 987.7 mbar

3212 3243 3206 3050 3006 Equipment ID #: 3183 3261 Cal. Due Dates: 2/19/14 5/7/14 12/21/13 2/19/14 5/8/14 6/21/13 3/25/14

Equipment ID #: 3128 Cal. Due Dates: 3/28/14 Product Model Number: XCC LOW COST CANOPY



Product Model Number: XCC LOW COST CANOPY Test #: 6515Q

